




Search our entire site!


[← BACK TO CATALOG START](#)
[← KEEP SHOPPING](#)

Quick Search



## STARTER ONE-WAY ASSEMBLY



Parts Included in the kit

Part Number **99999-03908-00****Online Price \$359.12**

List price \$422.49~ You save \$63.37!

Usually Ships Within 4 to 7 Business Days



### Details:

Slipping Starter problems on your V-Star 1100? This is a complete GENUINE YAMAHA kit with all necessary parts to upgrade the design of the Starter clutch, even the gasket! This new Starter Damper Assembly and Starter Clutch replaces the original idler gears and shaft and is supported on either end by needle bearings which will need to be installed into the crankcase and crankcase cover prior to installing the new damper assembly.

[Click HERE for a large picture and full parts list included in this kit](#)
[CLICK HERE TO READ THE YAMAHA TECH BULLETIN .pdf](#)
[CLICK HERE FOR INSTALLATION TIPS .pdf](#)

NOTE: Addressing the root cause for a starter one-way bearing failure will drastically reduce the possibility of engine kickback during starting. However, in the event that one of the conditions that cause engine kickback should occur in the future, this new Starter Damper Assembly will help minimize starter system wear during kickback.

Fits all Vstar 1100's, Bulldog and Dragstar

### Alternate Part Number(s):

999990390800

999-99039-08-00

### Suggestion Box

Your opinion is important to us at Yamaha of Cucamonga. If you have discovered an incorrect price, spotted a typo or encountered a technical problem on this page, we want to hear about it. Please include your email address if you would like us to reply.



Tags: starter, one-way, assembly, slipping, problems, v-star, 1100, complete, genuine, yamahakit, necessary, parts, upgrade

[Click HERE to go to our friendly URL page for this item](#)